

8

U.S. ENVIRONMENTAL PROTECTION AGENCY

NOTICE OF INSPECTION

30-045-10328

Address (EPA Regional Office) Region 9 Environmental Inspection Agency 75 Hawthorne Street (WTR-9) San Francisco, CA 94105	Inspection Contractor Navajo Nation EPA/Surface & Groundwater Protection Dept.- UNDERGROUND INJECTION CONTROL P.O. BOX 1999 SHIPROCK, NM 87420-1999	Firm To Be Inspected Vulcan Minerals & Energy 910 NMOC 1000 Rio Brazos Rd. Aztec, NM 87410
--	--	--

Date 7-27-04	Notice of inspection is hereby given according to Section 1445(b) of the Safe Drinking Water Act (42 U.S.C. §300 f et seq.).
Hour	

Reason For Inspection P & A completion @ Vulcan M & E HGU Well # 11

For the purpose of inspecting records, files, papers, processes, controls and facilities,
and obtaining samples to determine whether the person subject to an applicable
underground injection control program has acted or is acting in compliance with
the Safe Drinking Water Act and any applicable permit or rule.

NWSW Sec. 29, T31N, R16W
San Juan County, NM

RLS packer
Trip in & out of hole w/scraper — circulate
Set retainer @ 1114'
Pass pressure test @ 500 psi
Bottom plug:
Pump 38 sks of class III cement w/ 14.8 density
Plug from 1114' — 748' for depth of 366'
Perforate @ 152'

Top plug:
Pump 47 sks of class III cement w/ 14.6 density
Plug from 152' — surface
Set dry well marker w/ 10 sks of class III cement



Section 1445(b) of the SDWA (42 U.S.C. §300 j-4 (b) is quoted on the reverse of this form.

Receipt of this Notice of Inspection is hereby acknowledged.

Firm Representative Michael Higdon At Plus Contractor	Date 8-6-04 by Lee	Inspector Henry Villanueva - NMOC Wallace Ashley - NM Minerals
---	--------------------------	--