Deviation Report

Name of Company	Address	
Burlington Resources Oil & Gas Company	P.O. Box 4289, Farmington, NM 87499	
Lease Name and Number (API Number)	Location	Sec. Twn. Rge.
SAN JUAN 28-5 UNIT #41N (30-39 2 -7665)	1430 FNL -1925 FWL	32-028N-005W
Pool and Formation 27665	County	State
lanco Mesaverde/Basin Dakota	RIO ARRIBA	NEW MEXICO

(OH)

Depth (ft)	Deviation (degrees)
60	1.00
140	1.00
200	1.00
964	1.00
1,468	1.00
1,931	0.75
2,244	2.25
2,418	2.00
2,622	2.00
2,874	2.50
3,248	2.00
3,430	1.25
7,663	1.25



Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Subscribed and sworn to before me this 12th day of JuLY, 2004.

Notary Rablic in and for San Juan County, New Mexico

My commission expires September 15, 2004.