District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-144 June 1, 2004 or drilling and production facilities, submit to

Oil Conservation Division 2028 1220 South St. Francis Dr. Santa Fe, NM 87805 SEP 200

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Is pit or below-grade tank	de Tank Registration or Closur k covered by as "general plan"? Yes No or below-grade tank a Closure of a pit or below-grade	
	505 486-3041 e-mail address: jason.goss@dvn.con	r
Pit Type: Drilling Production Disposal Workover Emergency Lined Unlined Liner type: Synthetic Thickness mil Clay Pit Volume bbl	Below-grade tank Volume: 10 bbl Type of fluid: Produced Water Construction material: steel Double-walled, with leak detection? Yes ☒ If not, explain why not. Less than 50 feet (20 points)	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	50 feet or more, but less than 100 feet 100 feet or more	(10 points) (0 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points) (0 points)
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more Ranking Score (Total Points)	(20 points) (10 points) (0 points) 10 Points
If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal location: (check the onsite box if your are burying in place) onsite offsite If offsite, name of facility (3) Attach a general description of remedial action taken including remediation start date and end date. (4) Groundwater encountered: No Yes If yes, show depth below ground surface ft. and attach sample results. (5) Attach soil sample results and a diagram of sample locations and excavations.		
Additional Comments: Actual tank location is N 36°54.548' W 107°33.842' Well footages 790' FSL - 990' FWL	DEPUTY OIL &	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan . Date: August 2, 2004 Printed Name/Title Jason Goss/ Field Engineer Signature Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Approval: Printed Name/Title	Signature	Date: