submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT
Sundry Notices and Reports on Wells SEP 21 PM 12 12

· · · · · · · · · · · · · · · · · · ·			RECEIV	
4 T	638/-11		070 FARMING	TON BIA #14-20-603-734
	e of Well		6	. II IIIulaii, Ali. Oi
WIV	v			Tribe Name Navajo
			7	
2. Nam	ne of Operator			Horseshoe Gallup Unit
	Ican Minerals and Energy,	C/O NMOCD Aztec Dist	rict Office	more canap orm
			8	. Well Name & Number
3. Address & Phone No. of Operator				HSGU #66
1000 Rio Brazos Road, Aztec, NM 87410 505-334-6178				. API Well No.
			30-045-10235	
4. Location of Well, Footage, Sec., T, R, M				Field and Pool College Unit
660' FNL and 386' FWL, Section 33, T-31-N, R-16-W,				Horseshoe Gallup Unit County & State
000 TNE and 000 TWE, Section 05, 1-51-14, 14-10-44,				San Juan County, NM
			WEOLOSY -	can dain county, run
12. CHE	CK APPROPRIATE BOX T	O INDICATE NATURE O	F NOTICE, REPORT, OTHER	RDATA
Тур	e of Submission	Type of Action		
	Notice of Intent	X Abandonment	Change of Plans	
	Y Code a succest Dancet	Recompletion	New Construction	_
	X Subsequent Report	Plugging Back	Non-Routine Fracturing Water Shut off	1
	Final Abandonment	Casing Repair Altering Casing	Conversion to Injection	
•	Findi Abandoninent	Other -	Conversion to injection	
13. Des	cribe Proposed or Comple	eted Operations		
			ne above well NMSA 1978,	
	Purchase Agreement: 04	-521-0700028; Purchas	se Document: 04-199-0006	13.
8/11/04			Top ring holding slips frozen.	
8/12/04 No pressure. Work top ring free. Release packer. NU BOP with companion flange and tubing h test. TOH and LD 38 joints 2-3/8" tubing and packer. TIH with 36 joints A+ workstring and round-tri				
1/2" casing scraper to 1144'. TIH with tubing and attempt to set 4-1/2" DHS cement retainer. TIH with 4 more joints tubing and tag PBTD at 1235'. Set CR at 1235'. Sting out of retainer. Procedure change approved by Henry Villanueva, NMOCD. Establish circulation and circulate well clean with 20 bbls of				
				ll clean with 20 bbls of
			f) inside casing from 1235' to	o 670' to fill the Gallup
perforations. PUH to 300' and WOC. Shut in well.				
8/13/04 No pressure. TIH and tag cement at 802'. TOC approved by H. Villanueva. Load convature. Pressure test casing to 500#, held OK. TOH and LD tubing. Perforate 2 squ				
			Is of water. Pump additional	
			pe III cement (79 cf) pump d	
	150' to surface, circulate good cement out bradenhead. ND BOP. Dig out and cut off wellhead. Found			
	cement down 1' in casing and at surface in annulus. Mix 7 sxs cement to fill casing and install P&A			
	marker. H. Villanueva, NN	Ashley, Navajo	Minerals; and L. Lee, Navajo	EPA were on location.
	7111.7			
SIGNA		May Cont	ractor A	ugust 17, 2004 ACCEPTED FOR RECORD
	William F. Clark			ACCEPTED FOR RECORD
(This so:	ace for Federal or State Offi	ce use)		SEP 2 2 2004
APPRO		Title		Date
	ION OF APPROVAL, if any	•		FARMINGTON FIELD OFFICE
				BA
				HIMOCD