District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 South First, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM

87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa For No. 2777

Santa Fe, NM 87505

Submit 1 copy to appropriate
District Office
and 1 copy to the Santa Fe Office

(Revised 3/9/94)

PIT REMEDIATION AND CLOSURE REPORT

THE NEW COUNTY OF THE PROPERTY	
Operator: Burlington Resources Telephone: 505-326-9841	<u>নি</u>
Address: 3401 East 30th St., Farmington, NM 87402	(
Facility Or: MEXICO FEDERAL N Well No: 1 Pit No: 1 Well Name	
Location: Unit or Qtr/Qtr Sec F Sec 15 T 029N R 011W County San Juan	
Pit Type: tank (Separator, Dehydrator, Tank, Vent, Other)	
Land Type: <u>BLM</u> (BLM, State, Fee, Other)	
Pit Location: Pit Dimension length 12 width 12 depth 3	
Reference: wellhead Other	
Footage from reference: 25	
Direction from reference (azimuth): 260 degrees	
Depth To Ground Water:	
(Vertical distance from contaminants to seasonal Less than 50 feet (20 points)	
high water elevation of 50 feet to 99 feet (20 points)	
ground water.) Greater than 100 feet (0 points) $\underline{0}$	
Wellhead Protection Area: (Less than 200 feet from a private domestic water source, or; less than	
1000 feet from all other water Yes (20 points)	
sources.) No (0 points) $\underline{0}$	
Distance to Surface Water:	
(Horizontal distance to perennial Less than 200 feet (20 points)	
lakes, ponds, rivers, streams, creeks, 200 feet to 1000 feet (10 points) irrigation canals and ditches.) Greater than 1000 feet (0 points) o	
irrigation canals and ditches.) Greater than 1000 feet (0 points) $\underline{0}$	
RANKING SCORE (TOTAL POINTS): 0	

Mexico Feel N 1

Date Remediation Started	: <u>3/13/2002</u> Date completed:				
Remediation Method: (Check all appropriate sections.)	Excavation Approx. cubic yards:				
	Landfarmed Insitu Bioremediation				
	Other				
Remediation Location: (i.e. landfarmed onsite, name and location of offsite facility)	Onsite Offsite				
is detailed below. The	emedial Action: The lab data from the initial assessment of the pit pit is NOT located inside the OCD defined Vulnerable Area. Based K ANALYSIS, it is proposed to close the pit by backfilling with				
Ground Water Encountered	ed: No (yes or no) Depth:				
Final Pit: Closure Sampling: (if multiple samples, attach sample results and diagram of sample locations and depths)	Sample location center of pit Sample depth 3 Sample Date 3/13/2002 Sample time 11:10:00 AM Sample Results:				
	Benzene(ppm) <5				
Total BTEX(ppm) 265					
Field Headspace(ppm) 1397					
	TPH <u>3568</u>				
Ground Water Sample: No (If yes, attach sample results)					
I hereby certify that the inbelief. Date: 3/31/03	formation above is true and complete to the best of my knowledge and Signature Signature				
Title: Environmental Specialist Printed Name: Ed Hasely					

RISK ANALYSIS FOR EARTHEN PIT CLOSURE

Burlington Resources requests closure of the earthen pit at this location using a limited risk analysis based upon the following conditions:

- 1. The pit is <u>not</u> located inside the NMOCD defined Vulnerable Areas.
- 2. Groundwater is estimated to be at a depth greater than 100 feet.
- 3. The pit is <u>not</u> located within the Wellhead Protection Area within 200 feet of a private domestic water source or within 1000 feet of all other water sources.
- 4. The pit is located greater than 1000 feet to surface water.
- 5. The soils from below the pit bottom were analyzed and the only parameter above NMOCD closure guidelines was total BTEX, which exceeded 50 ppm. The benzene and Total Petroleum Hydrocarbons (TPH) levels were within the NMOCD closure guidelines.

Burlington Resources believes that the earthen pit poses minimal threat to groundwater, human health and the environment.

Client:

Burlington Resources

Project:

Pit Closure

Sample ID:

MEXICO FEDERAL 1 1139501

Lab ID:

0302W00969

Matrix: Condition:

Soil

Cool/Intact

Date Reported: 03/26/02

Date Sampled: 03/13/02

Date Received: 03/14/02

Date Extracted: N/A

	Analytical		
Parameter	Result	PQL	Units
BTEX - METHOD 8021B			
Benzene	<5	5	mg/Kg
Toluene	15	5	mg/Kg
Ethylbenzene	34	5	mg/Kg
Xylenes (total)	216	15	mg/Kg
Total BTEX	265	30	mg/Kg
GRO/DRO - METHOD 8015M			
Gasoline Range Organics(C6-C10)	3,193	50	mg/Kg
Diesel Range Organics (C10 - C22)	375	50	mg/Kg
Total Petroleum Hydrocarbons (C6-C22)	3,568	100	mg/Kg

Method 8021b, Volatile Organic Compounds, Test Methods for Evaluating Solid Waste, Physical/Chemical Methods, United States Environmental

Protection Agency, SW-846, Volume IB.

Reviewed By: