



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

MECHANICAL INTEGRITY TEST REPORT

(TA OR UIC)

Date of Test 9-30-04 Operator Benson Montu Greer API # 30-039 20372

Property Name Canada Ogilvie Unit Well # 18 Location: Unit C Sec 5 Twn 25 Rge 1 E

Land Type:

State _____
Federal ☒ _____
Private _____
Indian _____

Well Type:


Water Injection _____
Salt Water Disposal _____
Gas Injection ☒ _____
Producing Oil/Gas _____
Pressure observation _____

Temporarily Abandoned Well (Y/N): — TA Expires: _____

Casing Pres. _____ Tbg. SI Pres. 1230 Max. Inj. Pres. _____
Bradenhead Pres. TSTM- Ref of gas Tbg. Inj. Pres. _____
Tubing Pres. _____
Int. Casing Pres. _____

Pressured annulus up to 380 psi. for 30 mins. Test passed/~~failed~~

REMARKS:




By Ben L. Gonzalez
(Operator Representative)

Witness Bruce Montu
(NMOCD)

(Position)

Revised 02-11-02



GRAPHIC CONTROLS CORPORATION
BUFFALO, NEW YORK

CHART NO. MC MP-1000

METER _____ TAKEN OFF 10:15 A M

9/30/04
CHART PUT ON 9:45 AM

LOCATION C-5
MIT

REMARKS
Canada Digital Unit 18 (C-5)
Benson Martin Center
ADID 30-039-20372

BLG
B MG

PRINTED IN U.S.A.