

Deviation Report

| | | |
|---|---|---------------------------------------|
| Name of Company Burlington Resources Oil & Gas Company | Address P.O. Box 4289, Farmington, NM 87499 | |
| Lease Name and Number (API Number) SAN JUAN 29-7 UNIT #80M (30-039-27680) | Location -560 FSL -405 FWL | Sec. Twn. Rge. 09-029N-007W |
| Pool and Formation Blanco Mesaverde/Basin Dakota | County RIO ARRIBA | State NEW MEXICO |

(OH)

| <u>Depth (ft)</u> | <u>Deviation (degrees)</u> |
|-------------------|----------------------------|
| 260 | 1.25 |
| 500 | 2.00 |
| 860 | 2.00 |
| 1,359 | 2.75 |
| 1,640 | 2.75 |
| 2,110 | 1.00 |
| 2,582 | 1.00 |
| 3,054 | 1.00 |
| 3,525 | 1.00 |
| 3,760 | 1.00 |
| 7,995 | 1.50 |



Air Hammer Used? YES / NO

I, the undersigned, certify that I, acting in my capacity as Petroleum Engineer for Burlington Resources Oil & Gas Company, am authorized by said Company to make this report; and that this report was prepared under my supervision and directions, and that the facts stated herein are true to the best of my knowledge and belief.

Robert B. Tally

Subscribed and sworn to before me this 12th day of October 2004.

Kinsey Oltmanns

Notary Public in and for San Juan County, New Mexico

My commission expires September 22, 2008.