submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

BUREAU OF LAND MANAGEMENT		
Sundry Notices and Reports on Wells		
. Type of Well	1 13:UU 6 R	Lease Number 17 NMSF078399 17 Elf Indian, All. or
GAS	70 FA	R Tribe Name
Name of Operator	7.	Unit Agreement Name
BURLINGTON RESCURCES OIL & GAS COMPANY LP	-	San Juan 29-7 Unit
Address & Phone No. of Operator	- 8.	Well Name & Number
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	San Juan 27-4 Unit 66B API Well No.
Location of Well, Footage, Sec., T, R, M	-	30-039-26806
Sec., TN, RW, NMPM	10.	Field and Pool
Unit F (SENW), 2065' FNL & 2240' FWL, Sec. 22, T29N, R7W	11.	Blanco Mesaverde County and State
		Rio Arriba Co, NM
X Subsequent Report Plugging Non-Routine Fracturing Casing Repair Water Shut off Final Abandonment Altering Casing Conversion to Injection 3. Describe Proposed or Completed Operations		· · · · · · · · · · · · · · · · · · ·
10/14/04 RIH w/7-7/8" bit & Directional BHA. Tagged cmt @ 285'. D/O cement & then ahead to 64 reached 10/27/04. Circ. hole. RIH w/150 jts 4-1/2", 11.6#, L-80 LT&C casing and set @ 6416' w/st cement. Pumped 1 st stage – preflushed w/10 bbls gel water & 2 bbls FW. Lead – scavenger – 9 sx sca Lite w/6.25#/sx LCM-1, 1% FL-52, .3% CD-32, .25#/sx Celloflake. Tailed w/105 sx (208 cf-37 bbl w/.25#/sx Celloflake, .3% CD-32, 6.25#/sx LCM-1, 1% FL-52. Dropped plug & displaced w/20 bbls plug. Shut down @ 0215 hrs 10/28/04. Opened S/C @ 5902' & circ. between stages @ 5 bpm. Cir contaminated mud. 2 nd Stage – preflush w/10 bbls water/ 10 bbls mud clean & 10 bbls water. Lead i Premium Lite w/3% CaCl2, .25#/sx Celloflake, 5#/sx LCM-1, .4% FL-52, .4% SMS. Tailed in w/26/ Lite HS FM w/.25#/sx Celloflake, 3% CD-32, 6.25#/sx LCM-1 & 1% FL-52. Dropped plug and disp Bumped plug w/2140 psi, & closed stage collar. Plug down @ 0951 hrs. Pressured up on casing to 7 and circ. 42 bbls cement. 3 rd Stage – Preflush w/10 bbls water, 10 bbls mud clean & 10 bbls water. slurry) Premium Lite w/3% CaCl2, & .25#/sx Celloflake & 5#/sx LCM-1 & .4% FL-52 & .4% SMS. water. Bumped plug & closed stage collar. Circ. 50 bbls cement to surface. Cemented rat hole & RI 02200 hrs 10/18/04. Will show casing PT on next report. The Completion rig will conduct the PT be	age colla venger (slurry) P water & c. appron n w/225 l sx (517 laced w/ 00 psi & Lead w/ Droppe D BJ. NI	ar @ 2999' & 5902'. RU BJ to 11 cf - 5 bbls slurry) Premium remium Lite HS FM1 79 bbls mud. Didn't bump x. 150 bbls cement sx (479.5 cf - 85.4 bbl slurry) - cf-92 bbls slurry) Premium 60 bbls water & 3.17 bbls mud. opened stage collar @ 2999' 478 sx (1018 cf - 181.3 bbls d plug and displaced w/4.6 bbls D BOP, RD & released rig @
4. I hereby certify that the foregoing is true and correct.		
igned Talsy (lus) Patsy Clugston Title Sr. Regulatory	Specia	list Date 11/8/04 ACCEPTED FOR RECOI
This space for Federal or State Office use) PPROVED BYTitle		Date
CONDITION OF APPROVAL, if any: tle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of e United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.		Pariminatur Pield Offic