

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 5-12-04 Operator Dugan Production Corp. API # 30-043-20484
Property Name DOMED FED 10-22-7 Well No. 1 Location: Unit H Section 10 Township 22N Range 07W
Well Status(Shut-In or Producing) _____ Tubing 50 Intermediate _____ Casing 240 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>240</u>	Steady Flow		
10 minutes		<u>240</u>	Surges		
15 minutes		<u>240</u>	Down to Nothing		
20 minutes		<u>240</u>	Nothing	<u>X</u>	
25 minutes		<u>240</u>	Gas		
30 minutes		<u>240</u>	Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:


CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

By 
32 Switcher
(Position)

Witness _____



5-18-04. BH valve dug up + piped to surface - OK