

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-19-04 Operator Dugan Production Corp. API # 30-043-20506
Property Name DOMES TESORO 23 Well No. 1 Location: Unit L Section 23 Township 22N Range 07W
Well Status(Shut-In or Producing) Producing Tubing 3S Intermediate Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>0</u>	Steady Flow		
10 minutes		<u>0</u>	Surges		
15 minutes		<u>0</u>	Down to Nothing		
20 minutes		<u>0</u>	Nothing	<u>X</u>	<u>X</u>
25 minutes		<u>0</u>	Gas		
30 minutes		<u>0</u>	Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK


5 MINUTE SHUT-IN

BRADENHEAD

0

INTERMEDIATE

REMARKS:

By  Witness _____
32 Switcher
(Position)