

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-5-04 Operator H. K. Keesee API # 30-043-05257
Property Name MARGURITE Well No. 2 Location: Unit N Section 20 Township 23N Range 03W
Well Status(Shut-In or Producing) _____ Tubing 75# Intermediate _____ Casing 75# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>75#</u>	Steady Flow		
10 minutes		<u>75#</u>	Surges		
15 minutes		<u>75#</u>	Down to Nothing		
20 minutes		<u>75#</u>	Nothing	X	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN

BRADENHEAD 0#

INTERMEDIATE _____

REMARKS:

By

Carl A. Mike

Witness _____

17

Switcher

(Position)

