

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 5-27-04 Operator Dugan Production Corp. API # 30-039-22548  
Property Name S BLANCO NAVAJO 8 Well No. 1 Location: Unit A Section 08 Township 23N Range 07W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 58 Intermediate \_\_\_\_\_ Casing 58 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>58"</u>	Steady Flow		
10 minutes		<u>58"</u>	Surges		
15 minutes		<u>58"</u>	Down to Nothing		
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD 0

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Bill Armenta Witness \_\_\_\_\_

26

Switcher

(Position)

