

CII. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(806) 334-6178 FAX: (806) 334-6170
http://emnrd.etato.nm.ue/ocd/District III/3distric.ht

## **BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 12-08-0	Operator_	ENERDYNE LLC	API #30-0 <b>3</b>	1-05406	
Property Name CHACC	Wash Well No. 00	Location: Unit P	Section 21 Towns	hip 20N Range 9W	
Well Status(Shut-In of Proc	ducing) Tubing 5/8" I	intermediate NA Cas	ing 8" Branden	head NA	
OPEN BRADENHEAD A	ND INTERMEDIATE TO	ATMOSPHERE INDI	VIDUALLY FOR 15	MINUTES EACH	
PRESSURI	ES:		BRADENHEAD		
INTERMEDIATE TIME INTERMEDIA	ATE CASING		FLOWED	FLOWED	
5 minutes		Steady Flow			
10 minutes		Surges			
15 minutes		Down to Nothin	ng		
20 minutes		Nothing			
25 minutes		Gas	-	111111111111111111111111111111111111111	
30 minutes		Gas & Water_	<u> </u>	10 11 12 73	
		Water	60	OEC ST	
If bradenhead flowed water, ch	eck all of the descriptions	that apply below:	(C) (2)		
CLEARFRES	H SALTY	SULFUR BLA	ск 😓		
			The state of the s		
5 MINUTE SHUT-IN BRAI	DENHEAD	INTERMEDIATE	- Companies		
REMARKS: SHALLOW ME	NEFEE WELL THAT PRO	DUCES FRESH WATE	R WITH OIL- PRODU	ICTION CASING ONLY	
SURFACE CAS	SING OR BRADENHEAD.			-	
By DON L. HANOSH	Witness	S			
MANAGING MEMBER					