

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(506) 334-5170
http://emnrd.stato.nm.uslocal/District IM/2distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Property Name CHACO WASH Well No. 106 Location: Unit M Section: Well Status(Shut-In of Producing) Tubing Intermediate NA Casing OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUAL PRESSURES:	4.5" Bran UALLY FO BRADENI	or 15 MINUTES EACH		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDIO PRESSURES: INTERMEDIATE	UALLY FO	PR 15 MINUTES EACH		
PRESSURES: INTERMEDIATE	BRADEN			
INTERMEDIATE		HEAD		
	er Owen	BRADENHEAD		
TIME INTERMEDIATE CASING	FLOWED	FLOWED		
5 minutes Steady Flow				
10 minutes Surges				
15 minutes Down to Nothing				
20 minutes Nothing		·		
25 minutes Gas_				
30 minutes Gas & Water_		10 117		
Water				
If bradenhead flowed water, check all of the descriptions that apply below:	15			
CLEAR FRESH SALTY SULFUR BLACK				
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE		an a		
REMARKS: SHALLOW MENEFEE WELL THAT PRODUCES FRESH WATER WI	TH OIL- PR	ODUCTION CASING ONLY- NO		
SURFACE CASING OR BRADENHEAD.				

By DON L. HANOSH Witness_	Miles and the state of the stat			
MANAGING MEMBER (Position)				