

CH. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(506) 334-6178 FAX: (606) 334-6170
http://emmrd.otate.nm.ue/ocd/District III/3/distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test	12-08-04	Operator	ENERDYNE LLC	API #30-0	31-20767
Property Name	CHACO WAS	H Well No. 27	Location: Unit_	B Section 28 Tow	nship 20N Range 9W
Well Status(Shut-	In or Kroducing	Tubing 5/8"	Intermediate NA C	Casing 4.5" Brand	lenhead NA
OPEN BRADEN	IHEAD AND IN	TERMEDIATE T	TO ATMOSPHERE IN	DIVIDUALLY FOR	15 MINUTES EACH
PRESSURES:			BRADENHEAD		
INTERMEDIATE TIME INT	ERMEDIATE	CASING		FLOWED	FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing		
25 minutes		makanahakan kan angan angan angan angan angan angan angan ang ang	Gas		
30 minutes			Gas & Water	ſ	
			Water	<i>f</i> \$	2618911112
If bradenhead flower	d water, check al	of the description	s that apply below:		
CLEAR	FRESH	SALTY	SULFUR BI	LACK (2)	
5 MINUTE SHUT-IN BRADENHEAD		INTERMEDIATE			
REMARKS: SHAL	LOW MENEFE	E WELL THAT PF	RODUCES FRESH WAT	TER WITH OIL- PRO	DUCTION CASING ONLY- NO
		R BRADENHEA			
By DON L. HANG	OSH	Witn	ess		
MANAGING M (Position)	IEMBER				