

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test 12 22 - 0	✓ Operator	MAM Producti	<u>) </u>	05347
Property Name <u>Jicarilla</u> 13	Well No	Location: UnitS	ection <u>23</u> Towns	hip Range 5-W
Well Status(Shut-In or Producing	ng) Tubing 70	Intermediate 💆 Casi	ng 81 Branden	head
OPEN BRADENHEAD AND I	NTERMEDIATE '	TO ATMOSPHERE INDIV	/IDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes		Steady Flow		
10 minutes		Surges		
15 minutes V	4	Down to Nothing	g	
20 minutes		Nothing \		V
25 minutes		Gas		
30 minutes		Gas & Water		
		Water		
If bradenhead flowed water, check	all of the description	ns that apply below:		
CLEAR FRESH	SALTY	SULFUR BLAC	CK	
5 MINUTE SHUT-IN BRADENI	HEAD	INTERMEDIATE		
REMARKS:				
				
	<u> </u>			
1/2-2-1/		· · · · · · · · · · · · · · · · · · ·	 	
By Alonzo Harvey	Witr	ness	to the same to	•
Pumber (Position)	<u></u>			