

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## BRADENHEAD TEST REPORT

(submit 2 copies to above address)

	(0	espand ,	,	
Date of Test 12-22-09	/ Operato	r Mam Productio	n API #30-0 <u>39-</u>	21881
Property Name Vicar Ila 3	7 <u>B</u> Well No	Location: Unit	Section <u>24</u> Towns	hip <u>24·N</u> Range <u>5-</u> V
Well Status(Shut-In or Producing	ng) Tubing <u>65</u>	Intermediate O Ca	asing 75 Branden	head_ <i>O</i> _
OPEN BRADENHEAD AND I	NTERMEDIATE	TO ATMOSPHERE INI	DIVIDUALLY FOR 15	MINUTES EACH
PRESSURES: TIME INTERMEDIATE	CASING		BRADENHEAD FLOWED	INTERMEDIATE .FLOWED
5 minutes		Steady Flow_	······································	
10 minutes		Surges		
15 minutes V	V	_ Down to Not	hing	
20 minutes		Nothing		
25 minutes		Gas		
30 minutes		_ Gas & Water		
•		Water		
If bradenhead flowed water, check	all of the descriptio			
CLEAR FRESH			.ACK	
5 MINUTE SHUT-IN BRADENI	IEAD ·	INTERMEDIATE		
REMARKS:	<del></del>			
			•	
				-
By Alonzo Herry With		ness		
Pumply (Position)	·			