

(Position)

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District lil/3distric.htm

## BRADENHEAD TEST REPORT

(submit 2 copies to above address)

Date of Test	12/23/04	Operator	MAMPROD. OPER	<i>e.</i> api #30-0 <u>.39  </u>	23391
	•		Location: Unit <u>E</u>		
Well Status(S	hut-In or Producing	g) Tubing <i>/80</i>	Intermediate Cas	ing 300 Brandenh	nead <u> </u>
OPEN BRA	DENHEAD AND IN	TERMEDIATE 1	TO ATMOSPHERE INDI	VIDUALLY FOR 15	MINUTES EACH
TIME	PRESSURES: INTERMEDIATE	CASING	•	BRADENHEAD FLOWED	INTERMEDIATE FLOWED
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothi	ng	
20 minutes			Nothing		
25 minutes			Gas		
30 minutes			Gas & Water_		
			Water		
If bradenhead f	lowed water, check al	l of the description	ns that apply below:		
CLEAR FRESH SALTY SULFUR BLACK					
	. ·				·
•	UT-IN BRADENH	EAD	INTERMEDIATE		
REMARKS:		·			
Ву		Witne	ess		
Billy Karton Day					