



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 12-8-04 Operator SYNERGY OPERATING API #30-039-20649

Property Name 29-4 GORSEN 11 Well No. 2 Location: Unit N Section 11 Township 29N Range 4W

Well Status (Shut-In or Producing) Tubing 170 Intermediate 0 Casing 360 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:		BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING		
5 minutes	<u>0#</u>	<u>625#</u>	Steady Flow	
10 minutes	<u>0#</u>		Surges	
15 minutes	<u>0#</u>		Down to Nothing	
20 minutes			Nothing	<u>0#</u>
25 minutes			Gas	
30 minutes			Gas & Water	
			Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

NO PRESSURE ON BRADENHEAD



By

Donnell S. 1248  
LEASE OPERATOR  
(Position)

Witness

John O. Papp