



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/03/04 Operator CDX GAS LLC API # 3003906258
Property Name Jic Gas Com B1 Location: Unit 6 Section 31 Township 26N Range 5W
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 158 Intermediate _____ Casing 170 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	<u>0</u>	<u>170</u>										
10 minutes		<u>170</u>										
15 minutes		<u>170</u>										
20 minutes		<u>170</u>										
25 minutes		<u>175</u>										
30 minutes		<u>178</u>										
5 minute SI	<u>↓</u>	<u>182</u>										

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

BH had some psi but not enough to read on gauge.

Jane Montoya
Field Tech.

(Position)

Witness _____

NMOCD Test Area: C

