



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-24-04 Operator C.D.X Rio LLC API # 3003906561

Property Name Jic Apache 102#3 Location: Unit K Section 9 Township 2.6 Range 4
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 60# Intermediate Casing 30# Bradenhead 10#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor
5 minutes	5#	55#			
10 minutes	7#	50#			
15 minutes	9#	40#			
20 minutes	10#	30#			
25 minutes	10#	20#			
30 minutes	11#	20#			
5 minute St	11#	20#			

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing	X 1 min	
No Flow		
Gas	X	
Gas and Water		
Water		


If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 5# Intermediate

REMARKS:

B



y Harry Whitson
Tech T.P.S
(Position)

Witness Danell Spear T.P.S

NMOCD Test Area: