



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/03/04 Operator CDX. GAS LLC API # 3003908097
Property Name ICARILLA #A7 Location: Unit NW 1/4 SW 1/4 Section 17 Township 26N Range 5W
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 20 Intermediate _____ Casing 0 Bradenhead 40

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Steady Flow	Surges	Down to Nothing	No Flow	Gas	Gas and Water	Water
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor							
5 minutes	☒	☒										
10 minutes												
15 minutes												
20 minutes												
25 minutes												
30 minutes												
5 minute SI	☒	☒										

Bradenhead Flowed	Intermediate Flowed
☒	
☒	
☒	
☒	
☒	
☒	
☒	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

BH Took around 2 1/2 min to blow down to nothing.
Some gas was venting but not enough to measure on
gauge. Well is sanding up.

by Vince Montoya
Field Tech
(Position)

Witness _____