



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

12/03/04

Operator

CDX. GAS LLC

API #

3003922294

Property Name

JICARUA # BIE

NE 1/4 SE 1/4

Location: Unit

1

Section

22

Township

26N

Range

5W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

95

Intermediate

Casing

100

Bradenhead

68

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	100				Steady Flow	
10 minutes		85				Surges	
15 minutes		70				Down to Nothing	
20 minutes		70				No Flow	
25 minutes		70				Gas	
30 minutes		75				Gas and Water	
5 minute SI	✓	80				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

REMARKS:

BH blow down in 1 min. - venting gas not enough to measure on gauge. Piston came up while taking reading and well also vented.

by

Vince Montoya
Field Tech

Witness

(Position)

NMOCD Test Area: C