



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
[www.emnrd.state.nm.us/ocd/District 3/district3.htm](http://www.emnrd.state.nm.us/ocd/District%203/district3.htm)

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 12/27/04 Operator Elm Ridge Resources API #30-0 43-20711
Property Name Juquilla 393 Well No. B3 Location: Unit m Section 22 Township 23N Range 4W
Well Status (Shut-In or Producing) Tubing 64 Intermediate Casing 64 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	<u>0</u>		<u>64</u>	Steady Flow <u> </u>	
10 minutes	<u>0</u>		<u>64</u>	Surges <u> </u>	
15 minutes	<u>0</u>		<u>64</u>	Down to Nothing <u> </u>	
20 minutes				Nothing <u>X</u>	
25 minutes				Gas <u> </u>	
30 minutes				Gas & Water <u> </u>	
				Water <u> </u>	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK N/A

5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE

REMARKS:

5 min hole, no casing valve



By Kirk Duan

Witness

(Position)

E-mail address