

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC MM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ccd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test ARN 10 2005 Operator	ELM RIDGE BEJAPI #30-039.	-05214
Property Name AXI APACHE Well No. C-S	Location: Unit M Section 33 Towns	ship 24 Range 54
Well Status (Shut-In or Producing) Tubing 18	Intermediate Casing 58 Braden	head <u>O</u>
OPEN BRADENHEAD AND INTERMEDIATE TO	ATMOSPHERE INDIVIDUALLY FOR 1	5 MINUTES EACH
PRESSURES: TIME BRADENHEAD INTERMEDIATE CASING	BRADENHEAD PLOWED	INTERMEDIATI FLOWED
5 minutes	Steady Flow	
10 minutes	Surges	
15 minutes	Down to Nothing	
20 minutes	Nothing	
25 minutes	Gas	
30 minutes_	Gas & Water	,
•	Water	
If bradenhead flowed water, check all of the descriptions	that apply below:	
CLEAR FRESH SALTY	SULFURBLACK	5 26 27 33 2
5 MINUTE SHUT-IN BRADENHEAD REMARKS:	INTERMEDIATE	VAN 2305
1		
		1.01.6,20
By Amy Mysyn (Position)	Witness	
E-mail address		