

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 5-19-04 Operator Dugan Production Corp. API # 30-039-22494  
Property Name JO ANN'S JEWEL Well No. 2 Location: Unit L Section 17 Township 24N Range 02W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 70# Intermediate \_\_\_\_\_ Casing 210# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>210#</u>	Steady Flow		
10 minutes		<u>210#</u>	Surges		
15 minutes		<u>210#</u>	Down to Nothing		
20 minutes		<u>210#</u>	Nothing	<u>X</u>	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD 0#

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Carl D. Meeker Witness \_\_\_\_\_

17 Switcher  
(Position)

