

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division  
Aztec District Office  
1000 Rio Brazos Road  
Aztec, NM 87410  
(505)334-6178 FAX:(505)334-6170

**BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

Date of Test 5-19-07 Operator Dugan Production Corp. API # 30-039-22752  
Property Name JO ANN'S JEWEL Well No. 3 Location: Unit J Section 17 Township 24N Range 02W  
Well Status(Shut-In or Producing) \_\_\_\_\_ Tubing 10" Intermediate \_\_\_\_\_ Casing 8" Bradenhead 0"

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>80#</u>	Steady Flow		
10 minutes		<u>80#</u>	Surges		
15 minutes		<u>50#</u>	Down to Nothing		
20 minutes		<u>80#</u>	Nothing	<u>X</u>	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

**5 MINUTE SHUT-IN**

BRADENHEAD 0"

INTERMEDIATE \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By

Carl D. Mikes

Witness \_\_\_\_\_

17

Switcher

(Position)

