

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

(St	1011111 Z CO	pies to above address)
Date of Test 2/22/05	perator £	/4 felge fesous API #30-0 39-20661
Property Name Cento Deablas Well No. 7 Location: Unit O Section 10 Prownship 27 Range 44		
Well Status (Shut-In of Producing) Tubing 5 Intermediate Casing 15 Bradenhead 0		
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH		
PRESSURES: TIME BRADENHEAD INTERMEDIATE	CASING	BRADENHEAD INTERMEDIATE FLOWED FLOWED
5 minutes 0	15-	Steady Flow
10 minutes	15	Surges
15 minutes Ø	15	Down to Nothing 32425262 7
20 minutes		Nothing X
25 minutes		Gas (2075 7)
30 minutes		Gas & Water
		Water
If bradenhead flowed water, check all of the descriptions that apply below:		
CLEAR FRESH SALTY SULFUR BLACK		
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE		
REMARKS:		
+1		· W
By fel piece		Witness
(Position)	<u> </u>	
E-mail address	·	