

NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 2/1/05 Operator E/M Ridge Resorces API #30-0 43-20519						
Property Name for Nan 2 A Well No. 4 Location: Unit A Section Township Mange 3 W						
Well Status (Shut-In or Producing) Tubing 140 Intermediate Casing 210 Bradenhead 0						
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH						
TIME		PRESSURES: INTERMEDIATE	CASING		ADENHEAD OWED	INTERMEDIATE FLOWED
5 minutes_	0		310	Steady Flow		
10 minutes	0		210	Surges		
15 minutes	0		210	Down to Nothing	2	
20 minutes				Nothing O		
25 minutes				Gas		
30 minutes				Gas & Water	461	174757627
				Water		
If bradenhead flowed water, check all of the descriptions that apply below:						
CLEAR FRESH SALTY SULFUR BLACK						
5 MINUTE SHUT-IN BRADENHEAD INTERMEDIATE INTERMEDIATE						
REMARKS:						
			·			
By fich Dwa Pange (Position)				Witness		
	Pange					
E-mail add						