

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 4-21-04 Operator Dugan Production Corp API # 30-039-06032
Property Name HURT Well No. 3 Location: Unit B Section 14 Township 25N Range 03W
Well Status(Shut-In or Producing) Tubing 36 Intermediate _____ Casing 39 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>39</u>	Steady Flow		
10 minutes		<u>39</u>	Surges		
15 minutes		<u>39</u>	Down to Nothing		
20 minutes		<u>39</u>	Nothing	<u>X</u>	
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

By Carl D. Meeks
17 _____
Switcher
(Position)

Witness _____

