



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://nemrds.state.nm.us/ocdi/District IIU3district.htm](http://nemrds.state.nm.us/ocdi/District%20IIU3district.htm)

**BRADENHEAD TEST REPORT**

(submit 2 copies to above address)

Date of Test 8-19-04 Operator Minel Inc. API #30-0 39-22872

Property Name Cayias Well No. #1 Location: Unit G Section 2 Township 25 Range 3

Well Status (Shut-In or Producing) Tubing \_\_\_\_\_ Intermediate \_\_\_\_\_ Casing 15 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	INTERMEDIATE	CASING			
5 minutes			Steady Flow		
10 minutes			Surges		
15 minutes			Down to Nothing		
20 minutes			Nothing <u>XXX</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

**If bradenhead flowed water, check all of the descriptions that apply below:**

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALT \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN BRADENHEAD \_\_\_\_\_ INTERMEDIATE \_\_\_\_\_

REMARKS:

Change out valves and fittings on bradenhead

By Joe Elledge

Witness \_\_\_\_\_

Production Foreman \_\_\_\_\_  
(Position)

