

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

Oil Conservation Division
Aztec District Office
1000 Rio Brazos Road
Aztec, NM 87410
(505)334-6178 FAX:(505)334-6170

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-27-04 Operator Dugan Production Corp. API # 30-039-22948
Property Name SLICKHORN GULCH Well No. 2 Location: Unit M Section 08 Township 24N Range 07W
Well Status (Shut-In or Producing) Producing Tubing 5" Intermediate Casing 22" Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes		<u>22[#]</u>	Steady Flow		
10 minutes		<u>22[#]</u>	Surges		
15 minutes		<u>22</u>	Down to Nothing		
20 minutes			<u>Nothing</u>		
25 minutes			Gas		
30 minutes			Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Bill Amante Witness
26 Switcher
(Position)