

NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENTOIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emurd.state.nm.us/ocd/DistrictII/3district.htm>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 10-13-04 Operator ROBERT L. BAYLESS, PRODUCER LLC API #30-0 39-23542Property Name John S. Dashko Well No. 4 Location: Unit E Section 12 Township 24N Range 7WWell Status (Shut-In or Producing) _____ Tubing 150 Intermediate / Casing 150 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD	INTERMEDIATE
	INTERMEDIATE	CASING		FLOWED	FLOWED
5 minutes	<u>0</u>	<u>155</u>	Steady Flow	<u>No</u>	
10 minutes	<u>0</u>	<u>155</u>	Surges	<u>No</u>	
15 minutes	<u>0</u>	<u>160</u>	Down to Nothing		
20 minutes	<u>0</u>	<u>160</u>	Nothing	<u>X</u>	
25 minutes	<u>0</u>	<u>160</u>	Gas		
30 minutes	<u>0</u>	<u>162</u>	Gas & Water		
			Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

Looked Good

By _____

Witness _____

(Position)

