



AND NATURAL RESOURCES DEPARTMENT

MINERAL RESOURCES DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-04 Operator C DX Rio, LLC API # 300390552

Property Name Jicarilla Gas Com 35A#1 Location: Unit M Section 11 Township 24 Range 5
(Well Name and Number)

Pressure ~~(Shut-in or Producing)~~ Producing Tubing 90# Intermediate 95# Casing 95# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0#</u>						
10 minutes							
15 minutes							
20 minutes							
25 minutes							
30 minutes							
5 minute St							

Steady Flow
Surges
Down to Nothing
No Flow X
Gas
Gas and Water
Water

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0# Intermediate

REMARKS:

By Harry Whitson

Tech T.P.S

(Position)

Witness

Donald Spier T.P.S

NMOCD Test Area: