



AND NATURAL RESOURCES DEPARTMENT

AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-04 Operator C DX Rio, LLC API # 3003905569

Property Name Tecavilla Gas Com. 35B#1 Location: Unit H Section 11 Township 24 Range 5
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 75# Intermediate Casing 75# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH- Blowdown	Casing Monitor	Intermediate Monitor	Intermediate- Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0#</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow <u>-X</u>	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 0# Intermediate

REMARKS:

by

Harry Whitson
Tech T.P.S

(Position)

Witness

Samuel Spier T.P.S

NMOCD Test Area:

