



AND NATURAL RESOURCES DEPARTMENT

NEW MEXICO DEPARTMENT OF CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7-16-04 Operator C. D. X. Rio, LLC API # 3003923782

Property Name Jic. QP Tribal 35#7 Location: Unit H Section 2 Township 24 Range E
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 70# Intermediate _____ Casing 275# Bradenhead 0#

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH


Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH- Blowdown	Casing- Monitor	Intermediate- Monitor	Intermediate- Blowdown	Casing- Monitor	Flowed	Flowed
5 minutes	<u>0A</u>					Steady Flow	
10 minutes						Surges	
15 minutes						Down to Nothing	
20 minutes						No Flow <u>X</u>	
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute St						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____

5 Minute Shut-in Bradenhead 0# Intermediate _____

REMARKS:



By

Harry Watson
Tech T.P.S.

(Position)

Witness

Danell Spear T.P.S.

NMOCD Test Area: