

State Copy
(SUBMIT IN TRIPLICATE)


Budget Bureau No. 42-R-359.2.
Approval expires 12-31-55.

Indian Agency *Navajo*

14-20-600-3534

Allottee _____

Lease No. *62596*



UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL		SUBSEQUENT REPORT OF REDRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. *HX-165* is located *1885* ft. from *N* line and *2135* ft. from *E* line of sec. *9-12*, 19*58*
NE4 20 *32N* *16W* *NMPM*
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
San Juan *N.M.*
(Field) (County or Subdivision) (State or Territory)

The elevation of the *726* ~~derrick floor~~ above sea level is *5660* ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is proposed to plug and abandon this well as follows:

Plug No. 1 1690'-1950'
Plug No. 2 0'-85' (Surface pipe seat)
Erect marker and restore location to original contours.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company *SKELLY OIL COMPANY*

Box *408*

Address *Farmington, New Mexico*

Shiprock,

By *J. P. Clausen*

Title *Core Drill Sept.*