

Form 9-381D
APPROVED

AUG 15 1958

SAMUEL L. PLUMMER
Acting District Engineer

(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Indian Agency Nev.-Ute
14-20-600-3540
Allottee _____
Lease No. 62597

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL	SUBSEQUENT REPORT OF WATER SHUT-OFF
NOTICE OF INTENTION TO CHANGE PLANS	SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING
NOTICE OF INTENTION TO TEST WATER SHUT-OFF	SUBSEQUENT REPORT OF ALTERING CASING
NOTICE OF INTENTION TO REDRILL OR REPAIR WELL	SUBSEQUENT REPORT OF REDRILLING OR REPAIR
NOTICE OF INTENTION TO SHOOT OR ACIDIZE	SUBSEQUENT REPORT OF ABANDONMENT
NOTICE OF INTENTION TO PULL OR ALTER CASING	SUPPLEMENTARY WELL HISTORY
NOTICE OF INTENTION TO ABANDON WELL	

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

8-15, 1958

Well No. HX-163 is located 760 ft. from N line and 1980 ft. from W line of sec. _____

NWA 36 32N 17W KMPM
(1/4 Sec. and Sec. No.) (Twp.) (Range) (Meridian)
San Juan N.M.
(Field) (County or Subdivision) (State or Territory)

The elevation of the derrick floor above sea level is 5387 ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

It is proposed to plug and abandon this well as follows!

Plug No. 1 1740' to 1940'
Plug No. 2 1210' to 1480'
Plug No. 3 0 to 59' (Surface casing seat)

Erect marker and restore location to original contours.

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company SKELLY OIL COMPANY
Box 488
Address Farmington, New Mexico
Shiprock,

By J. R. Clance
Title Core Drill Sup't.

RECEIVED

AUG 15 1958

U. S. GEOLOGICAL SURVEY
FARMINGTON, NEW MEXICO

