



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-13-11 Operator Conoco Phillips API #30-0 39-21408

Property Name San Juan 29-7 Well No. 112 Location: Unit M Section 29 Township 29 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 199 Intermediate 668 Casing 202 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	—	668	204	208	204
10 min	—	668	204	79	205
15 min	—	668	204	26	205
20 min				5	205
25 min				0	206
30 min				0	206

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 1


REMARKS:

Bradenhead - Slight Puff
Intermediate didn't blow down completely in 30 min. still blowing enough to hear and feel.

By Juan Cardenas
Area 23 Run 353 MSO
(Position)

Witness Paul Wiebe

E-mail address _____



✓ Gas Anz. Well Sch.