



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-25-11 Operator Burlington API #30-0 39-30227

Property Name S.J. 29744 Well No 29M Location: Unit J Section 13 Township 24 Range 7

Well Status(Shut-In or Producing) Initial PSI: Tubing 165 Intermediate 18 Casing 183 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM.	
		Int	Csg	Int	Csg
5 min	0	19	184	4	186
10 min	0	19	185	0	186
15 min				0	186
20 min				0	186
25 min				0	187
30 min				0	187

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas		✓
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

B.H. 2 sec Puff when opened

Int. Blew down to dead 11 min 10 sec.

By Suzanne Hemphill

Witness Paul Wicks

(Position)

E-mail address _____

