



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT


(submit 1 copy to above address)

Date of Test 5-17-11 Operator Concepcion Phillips API #30-0 39-30497
Property Name Susana 26 4th Well No. 100M Location: Unit 18 Section 18 Township 29 Range 6
Well Status (Shut-In or Producing) (Producing) Initial PSI: Tubing 174 Intermediate 176 Casing 174 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
5 min				0	178
10 min				0	179
15 min				0	179
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		Vapor
Surges		
Down to Nothing		
Nothing	/	
Gas		
Gas & Water		
Water		



If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 20.7

REMARKS: Just blew head then to 900 in 3 seconds to vapors
Vapor at 5-10-15

BH nothing when opened
By Dusare Hemphill

Witness Monica Lucking

(Position)

E-mail address _____

Re-test in one month.