NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-2-11 Operator Burlington Res. API #30-0 45-26970

Property Name Rampart Canyon SWD Well No. 1 Location: Unit ___ Section 7 Township 30 Range 8

Well Status(Shut-In or Producing) Initial PSI: Tubing 1927 Intermediate N/A Casing -7.9 Bradenhead 1.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
TIME 5 min	0		-9.5		
10 min	0		-9.5		
15 min	0		-9.5		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

RCVD AUG 2 '11
OIL CONS. DIV.
DIST. 3

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: BH dead in 5 seconds

By Danny Nelson

(Position)

Witness Monica Kuehling

E-mail address _____