NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-2-11 Operator Burlington Res. API #30-0 45-28563

Property Name San Juan 32-9 Ut. SWD Well No. 5 Location: Unit ___ Section 18 Township 31 Range 9

Well Status(Shut-In or Producing) Initial PSI: Tubing 364 Intermediate N/A Casing -46 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE Bradenhead BH	Int	Csg	INTERM Int	Csg
TIME 5 min	0		-45		
10 min	0		-45		
15 min	0		-45		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	✓	
Nothing		
Gas	✓	
Gas & Water		
Water		

RCVD AUG 2 '11
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR_____ FRESH_____ SALTY_____ SULFUR_____ BLACK_____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Cleared at 17 seconds on 1/4" to 34 seconds 1"

By Danny Nelson Witness Monica Kuehling

(Position)

E-mail address _____