



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://omnrd.state.nm.us/ocd/District111/23/district.htm>

OIL CONS. DIV DIST. 3

MAY 01 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-23-13 Operator McLean midcont API #30-039-27796

Property Name Rincon Well No. 408 Location: Unit A Section 30 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 22 Intermediate X Casing 52 Bradenhead 165

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		53		
10 min	0		53		
15 min	0		53		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing <u>X 8sec</u>	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 6 INTERMEDIATE X

REMARKS: gas sample taken from csg + Braden Head

By Randy CalcoTE
calder service
(Position)

Witness _____

E-mail address Randy.C@calderservice.com

4-24-13