



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX. (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/18/2011 Operator Conoco Phillips API #30-0 3920712

Property Name San Juan 79-5 Well No. 68 Location: Unit A Section 18 Township 27 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 174 Intermediate 154 Casing 193 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min		154	193	0.1	197
10 min				0	198
15 min				0	200
20 min				0	201
25 min				0	202
30 min				0	203

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	<u>Intermittent 13 minutes</u>
Surges	
Down to Nothing	☒
Nothing	
Gas	☒
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD _____ INTERMEDIATE 2

REMARKS:

BH blew down in 2 seconds through 1" valve
Int had strong flow for the 1st 3 minutes, through 2" valve,
after 3 minutes, it had a steady, weak flow

By Garrett Wilson

Witness Moua Tschling

Production Engineer
(Position)

E-mail address garrett.a.wilson@conocophillips.com

