



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7/16/11 Operator ELPAMCO, INC API #30-0 45-07901

Property Name SULLIVAN Well No. 6 Location: Unit B Section 25 Township 29N Range 11W

Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate Casing 6 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>6</u>		
10 min	<u>0</u>		<u>7</u>		
15 min	<u>0</u>		<u>11</u>		
20 min	<u>0</u>		<u>13</u>		
25 min	<u>0</u>		<u>15</u>		
30 min	<u>0</u>		<u>15</u>		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

By Andy B. Russell
Inspector
(Position)

Witness

E-mail address

