Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018		
					<ol> <li>Lease Serial No. NMNM109385</li> <li>If Indian, Allottee or Tribe Name</li> </ol>		
							SUBMIT IN TRIPLICATE - Other instructions on page 2
1. Type of Well S Oil Well Gas Well Other					8. Well Name and No. VENADO CANYON UNIT 206H		
2. Name of Operator DJR OPERATING LLC Contact: SHAW-MARIE FORD E-Mail: sford@djrllc.com					9. API Well No. 30-043-21292-00-X1		
3a. Address 1600 BROADWAY SUITE 19	(include area code) 10. Field and Pool or Exploratory Area BASIN MANCOS						
DENVER, CO         80202           4. Location of Well         (Footage, Sec., 2)	11. County or Parish, State						
Sec 12 T22N R6W NWSW 13 36.148514 N Lat, 107.428619		SANDOVAL COUNTY, NM					
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
□ Notice of Intent	Acidize	🗖 Dee	pen	Production (Start/Resume		□ Water Shut-Off	
Subsequent Report	□ Alter Casing		Hydraulic Fracturing		ation	U Well Integrity	
	Casing Repair	_	v Construction	□ Recomplete		Other Drilling Operations	
□ Final Abandonment Notice	Change Plans		Plug and Abandon Plug Back		rarily Abandon Disposal		
13. Describe Proposed or Completed Op					*	vimate duration thereof	
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involve testing has been completed. Final A determined that the site is ready for	ork will be performed or provide d operations. If the operation re- bandonment Notices must be file	the Bond No. o sults in a multip	n file with BLM/BIA le completion or reco	. Required su mpletion in a	bsequent reports must be new interval, a Form 316	filed within 30 days 0-4 must be filed once	
Intermediate Casing and Cen	nent						
8/15/19 MIRU. Nipple up 11-i 11-inch 5K wellhead. (High T Braden Head, Pipe Rams, St test for 30 min on pre-set cas	ech Services) Test low 25 inger flex hose, all inner a ing, all tested good and re	50 psi for 5 m nd outer valv corded on ch	in, high 3000 psi es in choke mani art. Drill out 9.62	for 10 min: fold. 1500 p			
surface cement shoe track from 346 to 378 <u>Drill 8.75</u> intermediate 378 to 2000. 8/16/19 Drilling ahead 2000 to 4597 8/17/19 Circulated and sweep until shakers were clean. 8/18/19 Drilling ahead 8.75 curve 5330 to 5873 (casing point). TOH. Lay down directional tools					NMOCD		
clear floor. Run 139 joints of Pup joint set at surface. 1 Flo	7 inch 26# J55 LT&C inter	mediate casi	ng set at 5863 M	D 5247 TVE	D. 1 SEP 0 5 201	9	
					DISTRICT III		
14. I hereby certify that the foregoing i	Electronic Submission #	ERATING LL	, sent to the Far	mington			
Name (Printed/Typed) SHAW-MARIE FORD			Title REGULATORY SPECIALIST				
Signature (Electronic Submission)			Date 08/29/2019				
	THIS SPACE FO	DR FEDER	AL OR STATE	OFFICE U	SE		
Approved By ACCEPTED			JOHN HOFFMAN TitlePETROLEUM ENGINEER Date 09/04/2019				
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office Farmington				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent			erson knowingly and	willfully to m	ake to any department or	agency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISEI	0 ** BLM R	EVISED ** BLN		D ** BLM REVISE	D **	



## Additional data for EC transaction #481052 that would not fit on the form

## 32. Additional remarks, continued

## condition for cement.

,

8/19/19 Cement with Halliburton (60% excess on both Lead and Tail). 4500 psi test on lines. Test good. FW Spacer at 8.3# (10 bbls) followed by tuned spacer at 11.5# (30 bbls) followed by LEAD cement: from surface to 4178 at 12.3# 515 sx (175 bbls) of HALCEM, 1.95 yield at 10.36 gps. TAIL cement: from 4178 to 5863 (BOC) at 13.3# 312 sx (72 bbls) of VARICEM, 1.3 yield at 5.81 gps. Displace with 223 bbls of FW. Bump plug from 1350 to 1500 psi and hold for 5 min. 1 bbl back on bleed off. Floats held. Full spacer with trace of cement to surface. Shell Test (Wilson Services) Pipe rams, inner valves, TIW safety and dart valves against test plug. 250 psi low for 5 min and 3000 psi high for 10 min. All tested good and recorded on chart.