



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OCD Received
4/9/2020

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/oed/>

BRADENHEAD TEST REPORT
(Submit 2 copies to above address)

Date of Test 4-2-2020 Operator Logos Operating, LLC API # 3004535377

Property Name ROSA UNIT 552H Location: Unit C Section 9 Township 31 Range 6
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing NA Intermediate NA Casing NA Bradenhead NA

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>NA</u>	<u>NA</u>	<u>NA</u>			Steady Flow	
10 minutes	<u> </u>	<u> </u>	<u> </u>			Surges	
15 minutes	<u> </u>	<u> </u>	<u> </u>			Down to Nothing	
20 minutes	<u> </u>	<u> </u>	<u> </u>			No Flow	
25 minutes	<u> </u>	<u> </u>	<u> </u>			Gas	
30 minutes	<u> </u>	<u> </u>	<u> </u>			Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead NA Intermediate NA

REMARKS:

This Well is not been Drilled - There is only
Surface casing. No valves. Well is capped

By Mike Miller Witness _____
Lease Operator II
(Position)