AND NATURAL RESOURCES DEPARTMENT





OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC, NM 87410 (505 334-6178 FAX: (505) 334-6170 http://www.emnrd.state.nm.us/ocd/

## **BRADENHEAD TEST REPORT**

(Submit 2 copies to above address)

							,			
Date of Test	4-1	- 20	2 Operator		Logos	Operating,	LLC	API#30	003931329	
Property Name	е	ROSA UNIT 657H				Location: Unit A Section 25 Township 31 Range 6				
		(Well Name	and Number)						_	
Pressure (Shu	ut-in or Prod	ducing)	Tubing	NA	Interme	ediate <u>M</u>	A Casing A	)/4 Braden	head <u>NA</u>	
OPEN	BRADENH	EAD AND	INTERMEDIA	TE TO	ATMOS	PHERE IND	DIVIDUALLY FOR	15 MINUTES	EACH	
	Bradenhead			Intermediate			]			
Time	BH Blowdown	Casing Monitor	Intermediate Monitor		ermediate lowdown	Casing Monitor		Bradenhead Flowed	I Intermediate Flowed	
5 minutes			- Information	-	iowdowii	Wonter	Steady Flow		T	
10 minutes				-			Surges			
15 minutes				-			Down to Nothing			
20 minutes				-			No Flow			
25 minutes				-			Gas			
30 minutes				-			Gas and Water			
5 minute SI				-			Water			
Clear										
REMARKS: —	This	well	15 7	l p	set	only	/			
									-	
Ву	)avid	Dry	yer erator		Wit	ness				