



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OK. CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/11/33district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5/18/2020 Operator SAN JUAN RES API #30-045-32574

Property Name FLORA VISTA Well No. 19-3 Location: Unit P Section 19 Township 30^N Range 11^W

Well Status (Shut-In or Producing) Initial PSI: Tubing Ø Intermediate NA Casing 5 Bradenhead Ø

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead		INTERM		
	BH	Int	Csg	Int	Csg
TIME					
5 min	Ø		6	NA	
10 min	Ø		7		
15 min	Ø		8		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		
BRADENHEAD	INTERMEDIATE	
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Ø

INTERMEDIATE NA

REMARKS:

Pumped well.

By Andy Prada

Witness _____

(Position)

E-mail address _____